TECHNICAL EXHIBIT 2a WORKLOAD ESTIMATES

The charts and estimated data listed below are provided as a guide to the contractor in estimating manpower, workload, and for scheduling requirements. As such, they are only estimates and variations shall not constitute grounds for a claim against the Government.

CHANGE OF OCCUPANCY MAINTENANCE (3 YEAR AVERAGE BY MONTH)

MONTH	ESTIMATED COM UNITS
OCTOBER	43
NOVEMBER	47
DECEMBER	47
JANUARY	40
FEBRUARY	42
MARCH	43
APRIL	34
MAY	49
JUNE	. 72
JULY	60
AUGUST	. 56
SEPTEMBER	38

SERVICE CALLS (3 YEAR AVERAGE BY MONTH)

MONTH	EMERGENCY	<u>URGENT</u>	ROUTINE	TOTAL
OCTOBER	308	320	394	1,022
NOVEMBER	297	338	395	1,030
DECEMBER	287	356	360	1,003
JANUARY	334	390	455	1,179
FEBRUARY	261	353	469	1,083
MARCH	292	353	492	1,137
APRIL	303	343	492	1,138
MAY	397	375	517	1,289
JUNE	461	333	490	1,284
JULY ;	423	333	494	1,250
AUGUST	390	354	562	1,306
SEPTEMBER	287	296	469	1,052

VARIATION IN CONTRACT WORKLOAD

- a. If the quantifies of housing and/or dormitory units to be maintained change (either increase or decrease) from the quantity shown in Section B "Supplies or Services and Pricing Costs" or the PWS, an adjustment will be made to the monthly price. This adjustment shall be applied when the number of units available for maintenance changes due to a housing modernization contract where another contractor takes full responsibility for the housing unit(s) for 30 days or more.
- b. The government shall provide the contractor 30 days notice prior to adding or deleting units for maintenance and the adjustment will be effective on the day the unit(s) are added or deleted from service.

The amount of adjustment is determined by dividing the number of units cited in the schedule or PWS into the monthly price, then multiplying that figure by the number of units to added or removed from service. Where units are added or deleted during a given month, the price is adjusted by the number of calendar service days applicable.

SERVICE CALLS BY TYPES

(3 YEAR AVERAGE)

	G. MAINT	APPL.	<u>HEAT</u>	A/C
OCT	777	121	55	69
NOV	783	132	100	14
DEC	780	120	102	2
JAN	904	136	136	3
FEB	860	127	71	24
MAR	872	145	57	62
APR	890	116	23	109
MAY	951	138	8	192
JUN	880	131	2	271
JUL	896	120	1	234
AUG	976	139	3	188
SEP	804	129	17	103

TOTALS 10374 1553 576 1270

OCCUPANT CAUSED DAMAGES (3 YEAR AVERAGE)

YEAR	# OF OCDs	TOTAL DOLLAR AMOUNT
FY94	51	\$6,189.65
FY95	41	\$4,388.14
FY96	57	\$4,108.07

TECHNICAL EXHIBIT 2b

FACILITIES TO BE MAINTAINED

HOUSING AREA	TYPE OF FACILITY	NO. OF UNITS PER TYPE	TYPE CONSTRUCTION	NO OF BDRMS	NET SQUARE FEET
WHERRY	A 1	3	Wood Frame/Vinyl Siding	3	1,176
WHERRY	A2	4	Wood Frame/Vinyl Siding	3	1,238
WHERRY	A3	2	Wood Frame/Vinyl Siding	3	1,110
WHERRY	B1	10	Wood Frame/Vinyl Siding	3	1,348
WHERRY	B2	6	Wood Frame/Vinyl Siding	3	1,369
WHERRY	C1	. 20	Wood Frame/Vinyl Siding	2	1,002
WHERRY	C2	20	Wood Frame/Vinyl Siding	2	966
WHERRY	C3	30	Wood Frame/Vinyl Siding	2	986
WHERRY	C4	30	Wood Frame/Vinyl Siding	2	998
WHERRY	D1	43	Wood Frame/Vinyl Siding	2	1,026
WHERRY	D2	15	Wood Frame/Vinyl Siding	2	1,058
WHERRY	D3	23	Wood Frame/Vinyl Siding	2	981
WHERRY	D4	19	Wood Frame/Vinyl Siding	2	1,041
WHERRY	E1	5	Wood Frame/Vinyl Siding	3	1,35
WHERRY	E2	5	Wood Frame/Vinyl Siding	3	1,32
WHERRY	E3	7	Wood Frame/Vinyl Siding	2	1,155
WHERRY	E4	11	Wood Frame/Vinyl Siding	2	1,180
WHERRY	E5	5	Wood Frame/Vinyl Siding	2	1,228
WHERRY	E6	1	Wood Frame/Vinyl Siding	3	1,490
WHERRY	E7	7	Wood Frame/Vinyl Siding	2	1,160
WHERRY	E8	7	Wood Frame/Vinyl Siding	2	1,125
WHERRY	E9	1 `	Wood Frame/Vinyl Siding	3	1,358
WHERRY	E10	9 3	Wood Frame/Vinyl Siding	3	1,447
WHERRY	E11	3	Wood Frame/Vinyl Siding	3	1,427
WHERRY	E12	1	Wood Frame/Vinyl Siding	2	1,110
WHERRY	F1	16	Wood Frame/Vinyl Siding	2	1,112
WHERRY	F2	31	Wood Frame/Vinyl Siding	2	1,161
WHERRY	F3	41	Wood Frame/Vinyl Siding	2	1,112
WHERRY	G1	29	Wood Frame/Vinyl Siding	2	963
WHERRY	G2	3	Wood Frame/Vinyl Siding	2	1,051
WHERRY	H1	14	Wood Frame/Vinyl Siding	2	996
WHERRY	H2	4	Wood Frame/Vinyl Siding	2	1,051
WHERRY	H3	10	Wood Frame/Vinyl Siding	2	996
WHERRY	J1	20	Wood Frame/Vinyl Siding	2	988
WHERRY	J2	- 4	Wood Frame/Vinyl Siding	2	1,0

HOUSING AREA	TYPE OF FACILITY	NO. OF UNITS PER TYPE	TYPE CONSTRUCTION	NO OF BDRMS	NET SQUARE
WHERRY	K1	11	Wood Frame/Vinyl Siding	2	FEET
WHERRY	K2	2	Wood Frame/Vinyl Siding	2	1,018
WHERRY	K3	4	Wood Frame/Vinyl Siding	2 2	1,059
WHERRY	K4	3	Wood Frame/Vinyl Siding	2	1,087
WHERRY	L1	12	Wood Frame/Vinyl Siding	3	1,015
WHERRY	L2	5	Wood Frame/Vinyl Siding	3	1,281
WHERRY	L3	10	Wood Frame/Vinyl Siding	3	1,272
WHERRY	N1	13	Wood Frame/Vinyl Siding		1,294
WHERRY	N2	9	Wood Frame/Vinyl Siding	3 3	1,211
WHERRY	N3	7	Wood Frame/Vinyl Siding		1,245
WHERRY	P1	13	Wood Frame/Vinyl Siding	3 3	1,256
WHERRY	P2	9	Wood Frame/Vinyl Siding	3	1,320
WHERRY	S1	13	Wood Frame/Vinyl Siding	3	1,300
WHERRY	S2	11	Wood Frame/Vinyl Siding	3	1,206
WHERRY	T1	1	Wood Frame/Vinyl Siding	3	1,176
WHERRY	T2	1	Wood Frame/Vinyl Siding	3	1,356
WHERRY	U1	1	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding	3	1,310
WHERRY	X1	1	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding	3	1,790
WHERRY	X2	1	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding	. 3	1,501
WHERRY	Z1	1	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding		1,521
CAPEHART	2A	16	Wood Frame/Brick Exterior	3 3	1,393
CAPEHART	2B	70	Wood Frame/Brick Exterior	3	1,350
CAPEHART	3		Wood Frame/Brick Exterior	3	1,198
CAPEHART	4		Wood Frame/Brick Exterior	3	1,147
CAPEHART	6(UNRENOVATED)		Wood Frame/Brick Exterior	3	1,274
CAPEHART	6 (RENOVATED)		Wood Frame/Brick Exterior	4	1,154
CAPEHART	7A		Wood Frame/Brick Exterior	4	1,350
CAPEHART	7B		Wood Frame/Brick Exterior	4	1,450
CAPEHART	8		Wood Frame/Brick Exterior	3	1,350
CAPEHART	9		Wood Frame/Brick Exterior		1,261
CAPEHART	10		Wood Frame/Brick Exterior	3 4	1,303 1,524
CAPEHART	11		Wood Frame/Brick Exterior		1,654
CAPEHART	11A		Wood Frame/Brick Exterior	4 4	1,796
CAPEHART	12		Wood Frame/Brick Exterior		
BUNKER HILL	JA4A	50	Wood Frame/Vinyl Siding	4 4	2,059 1,309
BUNKER HILL	JA4B	20	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding		1,309
BUNKER HILL	JA4C (2-STORY)	20 84	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding	4	•
BUNKER HILL	SA4A	24	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding	4	1,267 1,415
BUNKER HILL	SA4A SA4B	22	Wood Frame/Vinyl Siding Wood Frame/Vinyl Siding	4 5	
	UP-D	44	wood Frame/villyr Siding	J	1,388

TECHNICAL EXHIBIT 2c

EQUIPMENT TO BE SERVICED AND APPLIANCES MAINTAINED

NUMBER OF UNITS	INSTALLED EQUIPMENT TYPE	FREQUENCY
1,303*	Central Air Conditioning/Heating	Annually (Oct - Nov) or COM
1	Humidifiers	COM
350**	Carbon Monoxide Detectors	Annually (Oct -
1,765	Smales Detactors	Nov) or COM
1,705	Smoke Detectors	Annually (Oct - Nov) or COM
1,287	Dishwasher	COM
1,287	Garbage Disposal	COM
1,287	Kitchen Exhaust Fan	COM
1,303*	Water Heaters	COM
1	Sump Pump (7 Knob Hill)	COM
1	Circulating Pump (231 Jupiter Ct)	COM

No of Units	Appliance Type	Inspection Frequency
1,287	Refrigerator	COM
2	Oven/cooktop (built-in)	COM
1,285	Range (free-standing)	COM

^{*16} Wherry housing units have 2 HVAC units and 2 water heaters per housing unit.

ESTIMATED APPLIANCE REPLACEMENTS

Appliance	Basic Year	Option Years
Туре		•
Range (30" Gas)	113	150
Range (40" Electric)	7	9
Oven/cooktop (built-in)	1	1
Refrigerator (20.5-21.4 CF)	120	160
Refrigerator (22-23 CF S/S	1	1
w/watter and ice)		

^{**}Carbon Monoxide detectors in all Bunker Hill houses, Capehart Phase IV, Wherry Phase I

TECHNICAL EXHIBIT 2d

PLAYGROUND EQUIPMENT TO BE SERVICED

BUNKERHILL

ADDRESS	AMOUNT
123 LUNAR BENCH	1
MAXIWHIRL	1
SLIDE	1
LARGE DUASCAPE W/SWINGS	1
133 LUNAR	
SWING SET	1
128 LUNAR	
BENCH SWING SET	3 1
EAGLE PERCH W/SWIRL SLIDE	1
BUCK-A-BOUT	1
SMALL DUASCAPE	1
STUMP WALK	1
3-WAY CHIN-UP GEODESIC CLIMBER	1
GEODESIC CLIMBER	1
120 MERCURY	
ROCKET	1
128 SATURN BENCH SLIDE	
BENCH	4
SLIDE SNAIL	
WOODEN SWING SET	1 1
BUCK-A-BOUT	1
MAXI WHIRL	1
LEVEL BALANCE BEAM	1
BASKETBALL BOARD AND POLES	2
138 SATURN	
BENCH	2
WUM	1
BUCK-A-BOUT LARGE DUASCAPE	1 1
LANGE DUAJUARE	1

MAXI WHIRL

CAPEHART

ADDRESS	AMOUN ⁻
301A TALOS BASKETBALL BOARD AND POLE SLIDE MONKEY BARS SWING SET	2 1 1
229 FALCON SWING SET SLIDE MONKEY BAR	1 1 1
MAXI WHIRL ROCKING HORSE AIR PLANE BENCH	1 1 1 1
202A POLARIS SWING SET SLIDE MONKEY BARS	1 1 1
601 EAGLE SWING SET MAXI WHIRL SLIDE MONKEY BARS ROCKING HORSE AIR PLANE BENCH	1 1 1 1 1
131 FALCON MONKEY BAR (RAINBOW ARCH CLIMBER)	1
107 FALCON SWING SET	1
102 ATLAS - ATLAS PARK BASKETBALL BOARD AND POLE MODULAR PLAY STATIONS WHICH INCLUDE SWINGS, SLIDES, CARGO	9 3

NETS AND TUNNELS

CAPEHART

ADDRESS	AMOUNT
102 ATLAS - ATLAS PARK (CONT) ARCH TIRE SWING ALL PURPOSE COURT W/TENNIS NET SAND VOLLEY BALL PIT W/NET PICNIC SHELTER (20' X 20')	1 1 1
PICNIC SHELTER (12' X 12') CONCRETE DRINKING FOUNTAINS	1 2
105 JUPITER SWING SET	1
109 JUPITER MONKEY BARS (RAINBOW ARCH CLIMBER)	1
203A CENTURY AIRPLANE	1
DUCK ROCKING HORSE	1
BASKETBALL BOARD AND POLE	1 1
MONKEY BARS	1
SLIDE	1
BENCH SWING SET	1 1
125A CENTURY	
AIRPLANE DUCK	1 1
ROCKING HORSE	1
SLIDE	1
BENCH SWING SET	1
MONKEY BARS	1 .
MAXI WHIRL	1
202A CENTURY MONKEY BARS	,a
208A TITAN	1

SWING SET 1 SLIDE 1

CAPEHART

ADDRESS	AMOUNT	ĺ
203B MATADOR MONKEY BARS (RAINBOW ARCH CLIMBER)	1	
117B MATADOR SLIDE	1	
111B/113A PIONEER SWING SET	1	
105B PIONEER BUCK-A-BOUT	1	۸ .
103B THOR SLIDE	1	
208A PIONEER SLIDE	. 1	
208B THOR SLIDE	1	
105B THOR MONKEY BARS	1 · · ·	
119 CENTURY SWING SET	1	

ADDRESS 2 CHILDRESS	AMOUNT
BASKETBALL BOARD AND POLE	1
12 CHILDRESS SWING SET SLIDE AIRPLANE ROCKET	1 1 1 2
44B CHILDRESS SWING SET SLIDE AIRPLANE TEETER TOTTER BENCH	1 1 2 1 1
4A ASH SWING SET SLIDE BUCK-A-BOUT	1 1 1
4B ANDERSON SWING SET SLIDE BUCK-A-BOUT MONKEY BARS	1 1 1
12 ANDERSON SWING SET SLIDE BUCK-A-BOUT	1 1 1
18A BEAUMONT SWING SET SLIDE TEETER TOTTER BENCH	1 1 1

ADDRESS 22A BEAUMONT	AMOUNT
SWING SET SLIDE BUCK-A-BOUT TETHERBALL	1 1 1 1
4B POTEET SLIDE SWING SET BUCK-A-BOUT BENCH	1 1 1 1
5B ANDERSON SLIDE SWING SET BUCK-A-BOUT	1 1 1
17B NEHLS SLIDE SWING SET	1 1
64A CHILDRESS SLIDE SWING BUCK-A-BOUT BENCH	1 1 1 1
90A/92B CHILDRESS BASKETBALL BOARD AND POLE	1
105 CHILDRESS SLIDE SWING BUCK-A-BOUT BENCH	1 1 1

112 CHILDRESS

SLIDE
SWING SET
BUCK-A-BOUT

ADDRESS	AMOUNT
109B BEAUMONT SLIDE BUCK-A-BOUT SWING SET	1 1 1
89 BEAUMONT SWING SET BUCK-A-BOUT SLIDE BENCH	1 1 1 1
53 BEAUMONT SWING SET BUCK-A-BOUT SLIDE BENCH TETHERBALL	1 1 1 1
33B NEHLS BASKETBALL BOARD AND POLE	1
84 BEAUMONT ROCKET AIRPLANE SLIDE SWING SET BENCH BUCK-A-BOUT	1 1 1 1 1
13B FAULK ROCKET AIRPLANE SLIDE SWING SET	1 1 1

F41612 98 D0003

BENCH	1
BUCK-A-BOUT	1
9B FAULK BASKETBALL BOARD AND POLE	1

ADDRESS	AMOUNT
16B FAULK	,
SLIDE	1
SWING SET	1
BUCK-A-BOUT	1
	, '
38A NEHLS	
SLIDE	1
SWING SET	. 1
BUCK-A-BOUT	1
	7

TECHNICAL EXHIBIT 2e

MINOR DISASTER HISTORY

During the past four years approximately \$1,050.00 has been paid for minor disaster damage. This averages \$265.00 per year. Most damages result from high winds.